

PHASE 1 DETOURS

RAMP F – Continue on SR 0380 east 0.5 miles to the intersection with Baum Blvd. Turn left onto Baum Blvd. (still SR 0380 east) and go 0.75 miles to Liberty Avenue. Turn left onto Liberty Avenue and go 0.8 miles to intersection of Liberty and Bloomfield Bridge. End Detour.

BLESSING STREET to SR 0380 EAST (Trucks Only) – Turn left onto Ridgway Str. Go 0.55 miles to the intersection with Herron Avenue. Turn right onto Herron, go to light at Bigelow Boulevard. Turn right onto Bigelow Boulevard. End Detour.

SR 0380WB LEFT TURN TO BLESSING – From the Blessing Str./Bigelow Blvd. intersection, continue 0.55 miles on SR 0380 West to Herron Avenue. Turn left onto Herron. Go 200', take first left onto Ridgway Street. Go 0.55 miles to Blessing. End Detour

BLOOMFIELD BRIDGE NB Entrance –

- Blessing Street - Turn left onto Ridgway Str. Go 0.55 miles to the intersection with Herron Avenue. Turn right onto Herron, go to light at Bigelow Boulevard. Turn right onto Bigelow Boulevard (SR 0380). Go 0.9 miles on Bigelow to the intersection with Baum Blvd. Turn left onto Baum Blvd. (still SR 0380 east) and go 0.75 miles to Liberty Avenue. Turn left onto Liberty Avenue and go 0.8 miles to intersection of Liberty and Bloomfield Bridge. End Detour.
- Centre Avenue – From the Centre Ave. / Bigelow Blvd. intersection, continue east on Centre Ave. 0.15 miles to N. Craig Str. Turn left onto N. Craig, go 0.15 miles to Baum Boulevard. Turn right onto Baum Blvd. (SR 0380 east) and go 0.75 miles to Liberty Avenue. Turn left onto Liberty Avenue and go 0.8 miles to intersection of Liberty and Bloomfield Bridge. End Detour.

BLOOMFIELD BRIDGE SB to SR 0380 – From the Liberty Avenue intersection with Bloomfield Bridge, continue on Liberty Avenue 0.8 miles to Baum Blvd (SR 0380). Turn right onto Baum Blvd. and go 0.75 miles to N. Craig Street. Turn right onto N. Craig Street (Still SR 0380) and go 0.4 miles to the intersection with Bloomfield Bridge. End Detour.

NEW DETOUR FOR PHASE 1A

SR 0380 WB (Baum Blvd and N. Craig Street) – From the N. Craig/Baum Blvd. intersection, turn right onto Baum Blvd. and go 0.75 miles to Liberty Avenue. Turn left onto Liberty Avenue and go 0.8 miles to intersection of Liberty and Bloomfield Bridge. Turn left onto Bloomfield Bridge on go 0.4 miles to Bigelow Blvd. (SR 0380). End Detour.

PHASE 2 – NO NEW DETOUR

PHASE 3 (2016) –

Baum Bridge Closure –

- SR 0380 EB – From N. Craig, go west on SR 0380 0.4 miles to Bloomfield Bridge. Turn right onto Bloomfield Bridge, go 0.4 miles to Liberty Avenue. Turn right onto Liberty Avenue, go 0.8 miles to the intersection with SR 0380 (Baum Blvd.) End Detour
- SR 0380 WB – From Millvale Avenue, go east on SR 0380 (Baum Blvd.) 0.45 miles to Liberty Avenue. Turn left onto Liberty Avenue and go 0.8 miles to Bloomfield Bridge. Turn left onto Bloomfield Bridge, go 0.4 miles to SR 0380 (Bigelow Blvd.). Turn left onto SR 0380 EB, go 0.4 miles N. Craig Street. End Detour.